

**CONDOR EARTH TECHNOLOGIES INC**

1739 Ashby Road, Suite B

Merced, CA 95348

Phone 209.388.9601

FAX 209.388.1778

www.condorearth.com

July 25, 2005

Kirk T. Larson, P.G.
California Regional Water Quality Control Board
11020 Sun Center Drive, #200
Rancho Cordova, CA. 95670-6114

**Subject: Monitoring Well Destruction Report, 9 California Street, Valley Springs
Condor Project No. 3651D**

Dear Mr. Larson:

Condor Earth Technologies, Inc. (Condor) observed the destruction of the groundwater monitoring well (MW-1) at 9 California Street (Site) in Valley Springs, California, (Figures 1 and 2, attached) on July 25, 2005. The monitoring well was destroyed in general accordance with the *Monitoring Well Destruction Work Plan* dated June 16, 2005.

The monitoring well was destroyed by Fisch Environmental (C57 #683865) of Valley Springs, California. The location of the well is shown on Figure 2, attached. Well construction details are shown in Table 1.

Table 1 Monitoring Well Construction Details

Monitoring Well	Date Installed	Total Depth (ft.)	Boring Diameter (in.)	Casing Diameter (in.)	Screen Interval (ft)		Grout Seal (ft)		Bentonite (ft)		Filter Pack (ft)	
					From	To	From	To	From	To	From	To
MW-1	5-17-04	10	8	2	5	10	0	2	2	4	4	10

Condor obtained a well destruction permit from the Calaveras County Environmental Health Department (CCEHD) prior to initiating fieldwork. The well was destroyed by pulling the well casing from the ground. The well boring was backfilled with neat cement grout. Asphalt coldpatch was placed on the upper part of the boring until it was level with the surrounding asphalt surface. The traffic box and other refuse from the well destruction were removed from the Site.

If you have any questions or need additional information, please call Lee Morse at (209) 388-9601.

Sincerely,


CONDOR EARTH TECHNOLOGIES, INC.



Kathy Vasquez
Staff Geologist



Lee H. Morse, P.G.
Associate Geologist




Attachments:


Figure 1 Vicinity Map
Figure 2 Site Map
Monitoring Well Destruction Permit


cc: David Reich, Valley Springs Partnership, LLC
Jason Boetzer, Calaveras County Environmental Health Department, San Andreas
Robert Hoffman, Caltrans


P:\3000_prj\3651 Noble UST Investigation\3651D Good Friends Groundwater Monitoring\Reports\Well Destruction Report.doc





 CONDOR EARTH TECHNOLOGIES, INC. 188 Frank West Circle, Ste Stockton, CA 95208 (209) 234-0518 f(209) 234-0538 www.condorearth.com stockton@condorearth.com	Job No.	3651D	VICINITY MAP GOOD FRIENDS RESTAURANT 9 CALIFORNIA STREET VALLEY SPRINGS, CALIFORNIA	FIGURE 1 File No. 3651D_F1
	Date	20 SEPT 2004		
	Scale	AS SHOWN		
	Drawn	ECV		



 CONDOR EARTH TECHNOLOGIES, INC. 188 Frank West Circle, Ste Stockton, CA 95208 (209) 234-0518 (209) 234-0538 www.condorearth.com stockton@condorearth.com	Job No. 3651D	SITE MAP GOOD FRIENDS RESTAURANT 9 CALIFORNIA STREET VALLEY SPRINGS, CALIFORNIA	FIGURE 2	
	Date 16 JUNE 2005			
	Scale AS SHOWN			
	Drawn AWA			Chk'd LM
	File No. 3651D_F2			

**WELL CONSTRUCTION APPLICATION****CALAVERAS COUNTY ENVIRONMENTAL HEALTH DEPARTMENT**891 Mountain Ranch Rd.
San Andreas, CA 95249(209)754-8399 - Phone
(209)754-8722 - Fax0405306
Application No.Owner's Name David ReichTelephone (209)532-9010Address P.O. Box 758

District No.

City, State, ZIP Soulsbyville, CA 953726-29-05
Application DateWell Driller Fisch EnvironmentalTelephone (209)772-3570July 25, 2005
Proposed Starting DateMailing Address 399 Sherin Place, Valley Springs CA 95252July 25, 2005
Proposed Completion DateLicense Type: C57License No. 683865 Renewal Date: 1/31/06Site Location 9 California Street, Valley Springs APN: 46-011-0733**WELL CONSTRUCTION REQUIREMENTS AND FEES ON REVERSE SIDE**TYPE OF WORK:
(Check)☐ New Well☐ Repair: (Deepening/Reconstruction/Modification)☒ Destruction/ClosureINTENDED USE:
(Check)☐ Drinking/Private☐ Cathodic☐ Test/Exploration Hole > 15-feet☐ Drinking/Public☐ Monitoring/Observation☐ Industrial☐ Commercial☐ Geothermal Heat Exchange☐ Agricultural

DISTANCE TO NEAREST:

Leach FieldLeach PitSeptic TankSewer LineProperty LineStream, Ditch /Drainage
Canal/Flood Plain

CONSTRUCTION METHOD:

☐ Cable Tool☐ Auger☐ Driven☐ Rotary☐ Other

DESTRUCTION OF WELL:

Casing Diameter 2"Approximate Depth 10'

DESCRIBE MATERIALS AND PROCEDURES:

Remove casing. Backfill with neat cement.

I understand that an approved permit and approved plot plan must be obtained and be on-site BEFORE any construction has begun. I also understand that approval of the water well construction does not guarantee water nor does it indicate whether this property is suitable for an individual sewage treatment and disposal system or that an approval to install such a system is granted.

SIGNATURE Lee H. Moore
(Owner, Agent, Driller)TITLE Associate Geologist DATE 6/28/05Receipt No. 152832**OFFICE USE ONLY**Received By: [Signature]Fees Paid: \$85.00Cash ☐Check ☒Date Received: 6-29-05**WELL CONSTRUCTION PERMIT**

This permit is not valid until the well site has been approved.

Inspections:

- ☒
- Site Approval
-
- ☐
- Seal Approval
-
- ☐
- Well Final

Date: 7-11-05

Inspected:

By JB

By

By

Water Quality Results:

Bacteria Test ☐Nitrate Test ☐

Longitude:

Latitude:

Comments: PLEASE CALL THIS DEPARTMENT AT LEAST
48 HOURS PRIOR TO COMMENCING WORK.

PERMIT SUBJECT TO COMPLIANCE WITH CALAVERAS COUNTY CODE, TITLE 8, CHAPTER 8.20

White - File

Canary - Other

Pink - Applicant/Well Driller

Cover Letter

Report/Document Title: Monitoring Well Destruction Report

Submittal Agencies: California Regional Water Quality Control Board, Central Valley Region
Calaveras County Environmental Health Department
Caltrans
Geotracker - California Electronic Data Submission for Environmental Sites

LUFT guidelines state that reports submitted to Local Implementing Agencies and the Regional Board should be accompanied by a cover letter, signed by the responsible party, acknowledging the statements, conclusions and recommendations included in the report. Any disagreement that the responsible party has with the contents of the report should be noted in the cover letter.

By signing below, I confirm that I have personally examined and am familiar with the information submitted in this report and all attachments, and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate and complete unless stated otherwise below.

I acknowledge that Condor Earth Technologies, Inc. has prepared the report listed above at my request. By signature below, I hereby authorize Condor to directly submit this report to the agencies listed above.

Authorized Representative:

David Rees

Date:

7-26-05

Requested report format for your copy: ☐ Hard Copy ☐ Electronic (PDF) Copy

Responsible Party Comments:

C:\Documents and Settings\leem\Desktop\Current Project Work\3651\LUFTReportSubmit Agreement -3651D.doc

